

REDACTED

From: Justin Quach/NA/BASF
To: Leon Zavodnik/BASF-CATALYSTS/BASF@BASF, Robert Scoggins/NA/BASF@BASF, Dennis Lucas/NA/BASF@BASF, Terrence M Vanderbosch/BASF-CATALYSTS/BASF@BASF
Date: 09/29/2014 04:12 PM
Subject: Sheave change PK Blender Dust Collector Fan

All,

I spoke with Mike Baron about changing the sheaves on this fan to speed it up to help our differential pressure problems. To do this, we will at some point need to shut it down and take the guarding off of the motor/fan to see what we currently have. When we cleanup for Selexsorb after making the last 9 pillmix batches would be a good opportunity to do so. Please let me know when the pillmix batches are complete and I will get Mike and myself up there to take a look. Thanks

Regards,

Justin Quach
Process Engineer - Catalysts

Phone: 440-329-2501, Mobile: 440-822-9800, Fax: 440-329-2403, E-Mail: Justin.Quach@basf.com
Postal Address: Catalysts Division, BASF Corporation, 120 Pine St, Elyria, OH 44035

BASF Corporation - The Chemical Company